



Site ID
City
Start No C2A
Location

Asset No. Report Section 03
Finish No C5
Location



Date 06/06/2011
Material Polyvinyl chloride (PVC)
Pipeline Length 0 m
Internal Diameter 189.7 mm



Junction



Junction




90% - Fractile: 0.5%, Exceeded limits: 52.1%



Site ID
City
Start No C2A
Location

Asset No. Report Section 03
Finish No C5
Location


Date 06/06/2011
Material Polyvinyl chloride (PVC)
Pipeline Length 0 m
Internal Diameter 189.7 mm



Junction



Junction



90% - Fractile: 0.5%, Exceeded limits: 52.1%