




Site ID	Asset No. Report Section 01	Date 06/06/2011
City		Material Polyvinyl chloride (PVC)
Start No C1	Finish No C2	Pipeline Length 0m
Location	Location	Internal Diameter 191.1mm

90% - Fractile: 0.6%, Exceeded limits: 51.4%



Comments