




Site ID
City
Start No C1
Location

Asset No. Report Section 01
Finish No C2
Location

Date 06/06/2011
Material Polyvinyl chloride (PVC)
Pipeline Length 0.0m
Internal Diameter 191.1mm

90% - Fractile: 192.0mm, Exceeded limits: 100.0%



Comments