




Site ID	Asset No. Report Section 01	Date 06/06/2011
City		Material Polyvinyl chloride (PVC)
Start No C1	Finish No C2	Pipeline Length 0m
Location	Location	Internal Diameter 191.1mm

Ovality 'q' (as per ASTM F 1216 Standard Practice) as a percentage of original pipe versus distance

90% - Fractile: 5.5%, Exceeded limits: 15.0%



Comments